



EARLY 911S E.K.
 WESTRING 416-418
 42329 WUPPERTAL
 GERMANY

TEL (+49) 202 76922 0
 FAX (+49) 202 76922 40

OFFICE@EARLY911S.DE
 WWW.EARLY911S.DE

Technical Data

Project No.	440
Mileage	39'540 km
Color	Slate Grey Metallic Schiefer Metallic
Color Code	9999
Interior Color	Vollleder Schwarz
Drive	LHD
First Registration	14.02.1985
FIN	WP0ZZZ93ZFS000356

€ 189.000,00

We will gladly support you with financing and leasing offers

Car Description

This accident-free Porsche 930 3.3 Turbo Coupé is in very good original condition. It has a beautiful patinated black interior that matches its age. The technology of the vehicle is in new condition. The exterior color is slate metallic declared as a special color with the code 9999. The vehicle was technical completely checked in our workshop and new tires were installed as part of the maintenance. The vehicle is offered with TÜV / AU and current Classic Data report.

First registration: 02/1985
 Vehicle type: 930970 / 3.3 Turbo Coupe
 Fin: WP0ZZZ93ZFS000356
 Engine type / no .: M930 / 66 67F00381
 Gearbox type / no .: 930/36 77F00291

The vehicle has the following individual equipment:

- 058 front and rear impact absorbers
- 197 More powerful battery
- 261 exterior mirror for passenger side -plan-, electrically adjustable and heated
- 383 sports seat left, electrically height adjustable
- 387 sports seat right, electrically height adjustable
- 462 Sekuriflex windscreen

Description (Cont'd)

498 Elimination of the model designation at the rear
650 Electric sunroof

Separate customization from the special request program:

SOW 021 GRP front spoiler
SOW 050 sports suspension
SOW 100 instrument holder and panel cover covered with leather
SOW 101 rosette for ignition lock with leather cover
SOW 102 fresh air nozzles in leather
SOW 103 instrument instrument in leather
SOW 104 control buttons covered in leather
SOW 106 hazard switch with leather cover
SOW 107 Operating handle for turn signal and wiper switches covered with leather
SOW 109 rosettes and knobs for interior door trim covered with leather
SOW 110 heating control regulation in leather
SOW 114 steering column trim covered with leather
SOW 115 3-spoke steering wheel type F / Ati with leather bozen
SOW 125 Conversion of operating switch Switch for heating regulation covered with leather
SOW 126 Installation of an outside thermometer in the center console
SOW 127 Installation of a voltmeter in the center console
SOW 128 Installation of a time clock in the center console
SOW 129 Electronic boost pressure display
SOW 130 shift sleeve covered in leather
SOW 134 handbrake lever upholstered in leather
SOW 137 Inner operating lever for door opener covered with leather
SOW 138 Sun visors left and right covered with leather
SOW 139 seat belt buckles covered with leather
SOW 149 installation of telephone system B
SOW 159 handset mounted on heating console with leather cover
SOW 160 roof antenna for telephone system
SOW 170 Shifter travel shortening

Please understand that a visit is only possible by appointment - please send an email: mh@early911s.de or mobile: 0049 172 88 40 640.

We have a vehicle fleet of over 400 vehicles.

Errors and changes excepted.